



NATURES OWN LUBRICATION & CORROSION PROTECTION

USER GUIDE

MIG RELEASE AGENT

Woolube Ozspray can save you many hours of lost production time by taking away those annoying and costly problems of **Spatter!!!**

BENEFITS: Long life metal protection
Component anti-spatter release agent
Anti-spatter agent for fabrication work benches
Spatter release agent for welding head

TECHNICAL:

1. With Mig shields, simply dip the heated end of the hand-piece in *Woolube Grease* or spray with *Woolube Ozspray* to prevent spatter adhesion. Repeat as necessary.
2. *Woolube Ozspray* should be left for 30 seconds to allow the hydrocarbon solvent to evaporate prior to welding.
3. Application of *Woolube Ozspray* to pre-fabricated components will greatly reduce the problem of spatter adhesion.
4. Clean off with steam cleaner or hot water wash above 60°C. *Woolube Enviro-Clean* has been specifically formulated to remove *Woolube Lanolin Products* without impact to the environment.
5. If painting, *Woolube Enviro-Clean* or thinners may be necessary to remove any excess *Woolube Lanolin Product*.

PO BOX 167 Berowra Heights, NSW 2082
Phone: 1300 664 663 Facsimile: 02 9456 6272
Email: info@woolube.com.au